

RC Nitro Troubleshooting Tuning Flowchart

This flowchart is based on several factors :

- 1) The motor is set to factory specs
- 2) The motor is warm, including the chassis
- 3) All parts are in working order
- 4) Carb is initially set to 1mm
- 5) Idle increases with clockwise rotation
- 6) Low and high-end mix richen with counter clockwise rotation

